



This June 14, 2007, photo made available by the Nuclear Regulatory Commission shows some of the extensive rust that accumulated on piping carrying essential service water at the Byron nuclear plant in Illinois. The water is needed to cool the reactor in an emergency. A leak in the system forced the plant to go offline for repairs later that year. (AP Photo/Nuclear Regulatory Commission)

[« Back to article](#)

Hosted by Google™