



This April 2006 photo made available by the Nuclear Regulatory Commission in response to a public records request by The Associated Press shows a badly rusted valve in a containment that was initially a focus of concern as workers tried to find the source of leaks at the closed Indian Point 1 reactor in New York state. The leakage was eventually traced to spent fuel pools. been shut down since 1974. (AP Photo/Nuclear Regulatory Commission)

[« Back to article](#)

Hoste