



This July 2007 photo made available by the Nuclear Regulatory Commission in response to a public records request by The Associated Press shows a badly rusted valve inside a vault at the Indian Point 1 nuclear plant in New York state. The pipe was part of a containment spraying system that was initially a focus of concern as workers tried to find the source of leaks at the site. Leakage was eventually traced to spent fuel pools. The reactor had been shut down since 1974. (AP Photo/Nuclear Regulatory Commission)

[« Back to article](#)

Hosted by